IP Camera - Lot - East (Left)

Test

Camera Commissioning Checklist

- ☐ Update Genetec License
- ☐ Ensure IP Address is configured or pulled an address
- ☐ Upgrade Camera Firmware
- ☐ Change account password
- ☐ Add camera to Genetec
- ☐ Configure camera streams to established standard
- ☐ Rename Unit and Camera
- ☐ Configure Motion Detection Settings using ACAP in 5.9 and up
- ☐ Verify Cameras Are Streaming Live
- ☐ Verify Camera is Recording
- ☐ Screenshot Approved View and/or Config Tool Thumbnail
- ☐ Enable enable Dynamic FPS and GOP (if supported)
- ☐ Confirm WDR is enabled
- ☐ Document Camera Hardware Details

Additional Info

OAK
- ☐ Stratocast Camera
- ☐ SD Card Installed

Share Password

Contact	Choose a contact ▼

Optional Encryption Key [   ]

Expires In [1 Day ▼]

[Close] [Share]

General

			DeviceType	IP Camera
DeviceType	IP Camera			
Site	Corporate Office			
Site	Corporate Office			

Share Password

Contact [Choose a contact ▼]

Optional Encryption Key [   ]

Expires In [1 Day ▼]

[Close] [Share]

Management

Device Management has been updated in version 4. click here to open in V4.

Network Interfaces

IP Address	IP Network	Subnet Mask	Description	Mac Address	Switch Port
10.41.215.119	☐ Elkhorn North - PCI-Security	255.255.255.0/24	PP-H20	AC:CC:8E:6E:31:76	

Hardware

Hostname	Lot - East (Left)		
Hostname	Lot - East (Left)		
Manufacturer	AXIS	Make/Model	Q3709-PVE (Left)
Manufacturer	AXIS		
Make/Model	Q3709-PVE (Left)		
		Serial	AC-CC-8E-6E-31-76
Serial	AC-CC-8E-6E-31-76		

Notes

Hello

Service	Description

-
-
-
-
-
-
-
-
-
-
-
-
-
-
-
-
-
-

-
- [Remove](#)

All Interactions

-
-
-
-
-
-
-
-
-
-
-
-
-
-
-
-
-
- [Remove](#)

Configurations

Config Type	Configuration	Description

Created: 6/29/2018 1:51:39 PM
Nickolas Nabower

Device - Lot - East (Left) - IP Camera - Prime Communications, Inc.

Last Modified: 1/29/2020 8:10:33 AM
Nickolas Nabower